K-195 Thornton Chestertown Private

1780

Thornton is a fine late 18th century plantation house of brick. The main house is five bays wide with two rooms per floor and a central hall. The kitchen wing also brick is covered with a catslide roof. The house retains an unusual amount of original trim and detailing, including a fine later porch. The interior is a treasure of original woodwork and painted graining. This decoration is now valuable and rare; having passed from favor in the 20th century, much of it was painted over and damaged. It has survived at Thornton, however, and in almost perfect condition. The house was built by the Brooks family, by whom it is still owned.

. .

INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

1 NAME HISTORIC AND/OR COMMON Thornton 2 LOCATION STREET & NUMBER Perkins Hill Road CITY. TOWN Chestertown STATE Maryland 3 CLASSIFICATION CATEGORY OWNERSHIP STATUS	L DISTRICT	
Thornton LOCATION STREET & NUMBER Perkins Hill Road CITY. TOWN Chestertown STATE Maryland CLASSIFICATION AND/OR COMMON CONGRESSIONAL First COUNTY Kent	L DISTRICT	
Thornton 2 LOCATION STREET & NUMBER Perkins Hill Road CITY. TOWN Chestertown STATE Maryland CLASSIFICATION Thornton CONGRESSIONA First COUNTY Kent	L DISTRICT	
2 LOCATION STREET & NUMBER Perkins Hill Road CITY TOWN Chestertown STATE Maryland CLASSIFICATION 2 VICINITY OF First COUNTY Kent	L DISTRICT	
Perkins Hill Road CITY TOWN Chestertown STATE Maryland CLASSIFICATION STREET & NUMBER CONGRESSIONAL CONGRESSIONAL CONGRESSIONAL COUNTY Kent	L DISTRICT	
Perkins Hill Road CITY TOWN Chestertown STATE Maryland CLASSIFICATION CONGRESSIONAL First COUNTY Kent	L DISTRICT	
Chestertown Chestertown STATE Maryland CLASSIFICATION CONGRESSIONAL First COUNTY Kent	L DISTRICT	
Chestertown STATE Maryland CLASSIFICATION CLASSIFICATION Chestertown X VICINITY OF First COUNTY Kent	E DISTRICT	
Maryland CLASSIFICATION		
3 CLASSIFICATION		
CATEGORY OWNERSHIP STATUS		
	PRESENT USE	
DISTRICTPUBLICAGRICULTI		
X_BUILDING(S) X_PRIVATEUNOCCUPIEDCOMMERC		
STRUCTUREBOTHWORK IN PROGRESSEDUCATIOSITE PUBLIC ACQUISITION ACCESSIBLEENTERTAIN		
OBJECTIN PROCESSYES RESTRICTEDGOVERNM		
BEING CONSIDEREDYES: UNRESTRICTEDINDUSTRIA	ALTRANSPORTATION	
X _{NO} MILITARY	OTHER	
4 OWNER OF PROPERTY		
NAME		
	:(301) 778-0595	
STREET & NUMBER		
Front Street CITY TOWN STAT	re, zip code	
	Maryland 21620	
5 LOCATION OF LEGAL DESCRIPTION Liber #: R	AS 30	
COURTHOUSE. Folio #:	545	
REGISTRY OF DEEDS, ETC. Kent County Courthouse	J4J 	
STREET & NUMBER		
CITY, TOWN STATE		
Chestertown Maryland	Marvland 21620	
THE Y HOLDS		
6 REPRESENTATION IN EXISTING SURVEYS		
6 REPRESENTATION IN EXISTING SURVEYS		
6 REPRESENTATION IN EXISTING SURVEYS		
G REPRESENTATION IN EXISTING SURVEYS TITLE DATE FEDERALSTATECOUNTY DEPOSITORY FOR	_LOCAL	
6 REPRESENTATION IN EXISTING SURVEYS TITLE DATE FEDERALSTATECOUNTY	-	



K-195

CONDITION

CHECK ONE

CHECK ONE

__EXCELLENT

X FAIR

__DETERIORATED
__RUINS
__UNEXPOSED

__ALTERED

X_ORIGINAL SITE
__MOVED DATE____

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

Thornton is a brick house and wing built in the late 18th century. It is located on Perkins Hill Road near Urieville and faces north across open fields. The main house is five bays wide and two and one-half stories high standing on a tall basement which is marked with a molded water table. The gable roof of the main house has two gable dormers in each roof slope. The chimneys are enclosed in gable walls and have corbelled and banded brick caps.

The wing is one and one-half stories high, one room deep and four bays long. It has a catslide gable roof extending above a shallow front veranda which is as long as the wing. The veranda roof rests upon four brick columns with bases marked by a course of molded bricks identical to those which make up the water table of the main house. The long slope of the roof is toward the rear of the building. Both slopes have gable dormers. A chimney is enclosed in the west gable wall. Another protruds from the center of the wing. Both have corbelled caps; the central chimney is extremely tall and slender.

The brick of the main house is laid in Flemish bond on the north (approach) facade, Liverpool bond on gables and rear, and English bond below the water table (which is found on the front, rear facades and on the east gable.)

Flemish bond mortar joints are grapevined. A belt course on the front facade has been chiseled away. Window openings on both front and rear have splayed flat arches; those in the attic have rowlock arches. The wing has Liverpool bond on all facades.

The main house is evenly fenestrated with 8/8 sash windows on the second floor, 12/8 sash windows on the first and three-pane windows used for cellar windows. There are central entrances, a 8/8 window at the stair landing, rear, and a tall window, now closed with louvered blinds above the main entrance. Second floor and basement windows have beaded frames with quarterround backband moldings; first floor frames on the south facade have quarterround moldings but are not beaded. On the north first floor and on the south entrance, frames have two planes instead of being flat, are beaded and have the usual quarterround backband. Sills on the second floor are flush with the walls, but those on the first are rounded and have a cove bed. (This detail is also seen at Knocks Folly, K-114) Louvered shutters are seen on second floor windows; on the first are three raised and beveled panel blinds which may be original.

Front and rear entrance doors have six raised and beveled panels on the outside; inside they have unusual horizontal battens which are beaded and grained and closed with late 19th century hardware. The north front entrance has a five pane transom light. It has architrave trim with triglyph corner blocks and paneled pilasters. There are full length louvered shutters. The jambs have flush beaded panels. The front entrance porch appears to be somewhat later than the house; its flat hipped roof is supported by double round columns. The balustrade has plain rectangular balusters and a molded handrail. The cornice has delicate, shaped modillion blocks. There are two benches.

Steps and rear porch are missing CONTINUE ON SEPARATE SHEET IF NECESSARY

8 SIGNIFICANCE

K-195

ERIOD	AREAS OF SIGNIFICANCE CHECK AND JUSTIFY BELOW			
PREHISTORIC	ARCHEOLOGY-PREHISTORIC	COMMUNITY PLANNING	_LANDSCAPE ARCHITECTURE	RELIGION
_1400-1499	_ARCHEOLOGY-HISTORIC	CONSERVATION	_LAW	SCIENCE
1500-1599	AGRICULTURE	ECONOMICS	LITERATURE	SCULPTURE
_1600-1699	X ARCHITECTURE	EDUCATION	MILITARY	_SOCIAL/HUMANITARIAN
X_1700-1799	ART	ENGINEERING	MUSIC	THEATER
_1800-1899	COMMERCE	_EXPLORATION/SETTLEMENT	PHILOSOPHY	_TRANSPORTATION
1900-	COMMUNICATIONS	_INDUSTRY _INVENTION	POLITICS/GOVERNMENT	Xother(specify) Interior design
SPECIFIC DATES c 1780		BUILDER/ARCH	HITECT Brooks Famil	v

Brooks Family

STATEMENT OF SIGNIFICANCE

Thornton retains an unusual amount of original trim and detailing on the exterior, but the interior is a treasure of early woodwork and decoration. Virtually all major features remain in place and most are decorated with painted graining. This decoration is extremely valuable and rare; having passed from favor in the 20th century, much of it was painted over and damaged. It has survived at Thornton, however, and in almost-perfect condition. The date of the graining is impossible to determine without paint analysis by an expert, however, the molding profiles are very sharp and in a damaged door in the parlor chamber only one color of paint, a bright, light blue, was visible, both of which would indicate that this was an early treatment, probably before

Thornton represents a fine country house of the end of the 17th century. Records in the Kent County Courthouse have a transaction of March 17, 1809 transfering the property (900 acres) from Mary Brooks to Phillip Brooks. A note gives the property its present name and stated that it previously belonged to another Phillip Brooks "late of Kent County." (B.C. 5/432) Whether the first Phillip was the builder of the house is unknown; the house has remained in the family until the present.

K-195

MAJOR BIBLIOGRAPHICAL REFERENCES

Earle, Swepson, The Chesapeake Bay Country, New York, Weathervane Books, repeat, originally published by the author, 1923.

Deed and Land Records, Kent County Court House, Chestertown, Maryland.

CONTINUE ON SEPARATE SHEET IF NECE	SSARY					
10 GEOGRAPHICAL DATA						
ACREAGE OF NOMINATED PROPERTY						
ACHEAGE OF NOMINATED PROPERTY						
VERBAL BOUNDARY DESCRIPTION						
	ES OVERLAPPING STATE OR COUNTY BOUNDARIES					
LIST ALL STATES AND COUNTIES FOR PROPERTIE	S OVERLAPPING STATE OR COUNTY BOUNDAMES					
STATE	COUNTY					
STATE	COUNTY					
III FORM PREPARED BY						
NAME / TITLE						
Marsha L. Fritz, Consultant						
ORGANIZATION	DATE					
Kent County Historical Society	August, 1977					
STREET & NUMBER	TELEPHONE					
Church Alley	STATE					
Chestertown	Maryland 21620					
CITED CET COMIT						

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature, to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 Supplement.

The Survey and Inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

RETURN TO: Maryland Historical Trust
The Shaw House, 21 State Circle
Annapolis, Maryland 21401
(301) 267-1438


7 Continued

Six sash windows are used on the wing which is also evenly fenestrated. Entrance doors are located in the east bay on front and rear and in the third bay from the east on the rear. Like the windows, frames have backband moldings made up of delicate composite curves. An additional entrance has been added to the gable. A portion of original cornice, made up of cyma recta and quarterround, remains on the rear.

The main house has a central hall and two rooms per floor. There are rooms on each floor of the wing and an enclosed stair. Most of the original woodwork remains in the house with the exception of the kitchen. Floors of medium to wide yellow pine also remain; most have not been painted, varnished or stained. Plaster, most in good condition and some fragments of wall paper, have also survived.

The stair is of the three run type and is open to the attic. The newel is very simple and turned as are intermediates. The newel cap is continuous with an oval, molded handrail. Balusters are rectangular, two per step. Step brackets have a scroll design up to the second floor and a curved slot above that. The spandrel is a simple rectangular panel with painted maple burl graining.

In the main, east parlor, the fireplace has a tabernacle overmantle. The mantle opening is rectangular with quarterround crossette surround. The straight mantle shelf has a curved bracket support. The room has crossette trim on the four windows and the door. Cornice, chairrail are sketched (not to scale) below.



The mantle has mahogany graining with black picking-out on ogee edge of panels. Panel fields are oak burl. Six-panel doors have oak graining with burl panels.

The west first floor room has identical chairrail and base-board, and trim except without crossettes. The paneled fireplace wall has recessed panels with ogee edges. There is a closet beside the fireplace.

The parlor chamber has a mantle with shelf supported by brackets and two flanking closets with six-panel doors. Paneling on this wall is recessed; the same chairrail as above is used but the window trim is a single quarterround. The west room on the second floor has a very similar paneled fireplace wall but the mantle shelf is supported by consoles.

7 Continued

Page 2

The first floor wing room has a more delicate trim made up of composite moldings and a mantle with broken shelf and three reeded freize blocks; there is a closet with vertical boards on the closet.

The main house appears to have been the first part constructed with wing added soon after. $\,$

Thornton is very similar to the house on the adjoining farm (K - 196). This house retains a great amount of its original frames, sash, shutters and interior woodwork and is a mine of 18th century detail. It even has its brick gutters on each side of the house to carry the water away from the foundations.

It is a five bay long, $2\frac{1}{2}$ story house, with a four bay long, $1\frac{1}{2}$ story wing. Basement brick is laid in English bond and there are four windows on both sides which retain original frames and sash set behind iron bars which are constructed into the masonry walls. There are flat arches above all windows. A quarter round molded brick forms the water table which encircles the house. There is no belt course. The center entrance has paneled jamb and door, transom and fluted pilasters and a good porch of the same period as the pilasters, a little later than the original house. There is also an entrance door on the second floor, leading onto the roof of the portico or porch. This latter door was probably a window originally. The windows have 12/12 sash on the first story 12/8 on second story and 6/6 in the "A" roof dormers, all of which appear original. There are original paneled shutters on the first story and louvered shutters on the second story. Within each gable is a very large chimney with good bold cap.

The brick wing is a very unusual treatment for a kitchen in Kent County. It is four bays long with three dormers on each side of the roof, neither side being symmetrical. The north side has a porch or arcade with brick floor laid on the ground, brick piers with quarter round watertable, which is flush with the main facade, thus setting the opposite side of the building about six feet forward of the south wall of the main portion. The roof is very steep on the south facade and is catalide on the north, in order to cover the arcade. The entrance to the basement of the main portion is under the cover of the arcade. The ceiling of the arcade has beaded slats with an air space between. Windows of the wing have 9/6 sash. There is a chimney on the outer gable and one in the middle of the structure which is very tall. A recent leanto porch has been installed on the south side.

The interior is almost all original but is in untouched condition. The parlor has window seats, broken pediment above the fireplace, dog ear trim, etc.


Over

The stair has a mahogany rail, turned newel and square balusters and ascends to the attic. Other rooms are simpler, but worthy of study. The wing contains the kitchen and presumably a dining room, with enclosed stair between.

This is one of the few houses in Kent which is in almost untouched condition.

And the second of the second o the state of the second of the and the second of the second o and the second of the second o 1. Nathan, I was to the second of Company of the Compan to a conservation of the c

 $\mathbf{e}^{-}}}}}}}}}}}}}}}}}}}}}}}$





THORNTON MHT 195

PERKINS HILL RD CHESTERTOWN, MD

FRONT - NORTH WEST

C. ENGSTROM AUG. 1977



THORNTON MHT 195
PERKINS HILL RD
CHESTERTOWN, MD.

HIGHER SECTION - STAIRWAY

C. ENGSTROM AUG 1977



Thanton M.H.T.195 Terkins Hill Rd. Chectertoever, Md.

First Hoss- Fall Section. Frained Loor at entrance to South Room C. Ting strone aug 1977



THORNTON MHT 195
PERKINS HILL RD

CHESTERTOWN, MD

MANTEL PANELLING - SECOND FLOOR - HIGHER SECTION

C. ENGSTROM AUG 1977